

Work Docket



Client Code: SRS01-001
Client Name: SRS Office PPM
Address: Unit 1 Northwest Centre
 North West Business Park

Parent Code: SRS01
Parent Name: SRS Office
Parent Address: Unit 1 Northwest Centre
 North West Business Park

ServiceCode: 2308
PO Number: PO 1237

Job ID:

Issue	Resolution
Q1 2020 Preventative Maintenance SRS061- Fire Hose Reels	Arrived on site as requested. All hose reels inspected throughout the site. All hose reels functionally tested. All dynamic and static pressures and flows tested using test kit and results noted on service label. All service labels and asset lists updated. Site contact advised of findings prior top departure.

Name	Started Travel	Arrival Time	Departure Time
Ronan Behan	26/04/2020 10:00:00	26/04/2020 10:30:00	26/04/2020 11:30:00

Quotation Required: No

Labour Hours:	01:00h
Travel Hours:	00:30h

Total Office Hours:	00:00h
Total Evening Hours:	00:00h
Total Night And Weekend Hours:	01:30h
Total Hours:	01:30h

SRS Office PPM

26/04/2020 12:01

Name: Ronan Behan

Name: Joe Bloggs

Procedure Plan - Service Hose Reels

Contract: n/a

Client: SRS Office PPM

Plant Item: /

Location: n/a

Serving: n/a

Model No: n/a

Serial No: n/a

All Hoses unwound, inspected and free of kinks	Yes
All Hoses free of visable damage	Yes
Hose nozzles checked and secure	Yes
Hose jubilee clips checked and secure	Yes
Spray settings checked and all functioning	Yes
Hose reel supply valve checked and functioning	Yes
All hose reels operated and functioning	Yes
All hose reels water pressure tested	Yes
All hose reels inspected	Yes
All hose reels securely fixed to the wall	Yes
All hose reels correctly sited	Yes
All hose reels are visable and unobstructed	Yes
All hose reels operating instructions are present	Yes
Where fitted booster pumps checked and funtioning	Yes
Status of the systems reported to contact	Yes
All hose reels serviced to IS EN 671-3	Yes
Comments	